

BRITTON MUNI (BTN) 2 NE UTC-6(-5DT) N45°48.90' W97°44.57'**TWIN CITIES**

1318 B S2 FUEL 100LL NOTAM FILE HON

L-14G

RWY 13-31: H4210X75 (ASPH) S-12.5 MIRL

IAP

RWY 13: PAPI(P4L)—GA 3.0° TCH 37'. Road.

RWY 31: PAPI(P4L)—GA 3.2° TCH 37'.

RWY 01-19: 2034X120 (TURF)

RWY 01: Fence.

RWY 19: Road.

AIRPORT REMARKS: Attended Mon-Fri daltg hrs. Waterfowl and gulls on and in/ov arpt. Rwy 19 +6' fence 190' from thld. Rwy 01-19 NSTD markings, marked with black and white cones. ACTIVATE MIRL Rwy 13-31—CTAF.

COMMUNICATIONS: CTAF/AUNICOM 122.8


MINNEAPOLIS CENTER APP/DEP CON 120.6

GCO 121.725 (4 clicks to MINNEAPOLIS CENTER and 6 clicks to FLIGHT SERVICES)

RADIO AIDS TO NAVIGATION: NOTAM FILE ABR.

ABERDEEN (H) VOR/DME 113.0 ABR Chan 77 N45°25.04'

W98°22.12' 041° 35.6 NM to fld. 1301/7E.

**BROOKINGS RGNL** (BKK) 0 SW UTC-6(-5DT) N44°18.29' W96°49.02'**OMAHA**

1648 B S4 FUEL 100LL, JET A Class IV, ARFF Index A NOTAM FILE BKK

H-21, L-121

RWY 12-30: H5231X100 (ASPH-PFC) S-39, D-54, 2S-83, 2D-76 HIRL 0.4% up SE

IAP

RWY 12: REIL. PAPI(P4L)—GA 3.0° TCH 49'. Railroad.

RWY 30: MALSR. PAPI(P4L)—GA 3.0° TCH 45'. Tree.

RWY 17-35: H3599X60 (ASPH) S-12.5 MIRL 1.1% up S

RWY 17: REIL. PAPI(P4L)—GA 3.0° TCH 27'. Railroad.

RWY 35: REIL. PAPI(P4L)—GA 3.0° TCH 24'. Road.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 12: TORA-5231 TODA-5231 ASDA-5231 LDA-5231

RWY 17: TORA-3599 TODA-3599 ASDA-3599 LDA-3599

RWY 30: TORA-5231 TODA-5231 ASDA-5231 LDA-5231

RWY 35: TORA-3599 TODA-3599 ASDA-3599 LDA-3599

AIRPORT REMARKS: Attended 1400-0000Z. For attendant after hrs call 605-692-2779 or 605-690-6013. Rwy 12 and Rwy 17 apch ends are closely aligned. Verify correct rwy and compass heading prior to dep. Deer on and in/ov arpt. PPR 48 hrs for unscheduled air carrier ops with 31 plus passenger seats call arpt manager (605) 697-8664. Rwy 17-35 not avbl scheduled ops involving air carrier acft designed for 10-30 passenger seats and unscheduled air carrier ops involving acft designed 30 plus passenger seats. Scheduled air carrier ops involving acft designed for 10-30 passenger seats and unscheduled air carrier ops involving acft designed for 31 plus passenger seats are not authorized under part 139 to operate at BKK in excess of 15 mins before or after scheduled arrival/departure times. Coordinate scheduled changes with airport manager to assure ARFF avbl call (605) 697-8664. Intensive student training. Wildlife on and in/ov arpt. Large flocks of geese and gulls on and in/ov arpt Apr-Oct. During summer months mowing and farming ops daltg hrs only. ACTIVATE HIRL Rwy 12-30, MIRL Rwy 17-35, MALSR Rwy 30, REIL Rwy 12, Rwy 17 and Rwy 35, PAPI Rwy 12, Rwy 30, Rwy 17 and Rwy 35—CTAF.

WEATHER DATA SOURCES: AWOS-3 108.8 BKK (605) 692-1809.**COMMUNICATIONS:** CTAF/UNICOM 123.0

RCO 122.65 (HURON RADIO)

GCO 121.725 (4 clicks to MINNEAPOLIS CENTER)

AIRSPACE: CLASS E svc Mon-Fri 1130-0130Z, Sat 1100-1300Z and 1900-2100Z, Sun 2100-0130Z other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE BKK.

(T) VOR/DME 108.8 BKK Chan 25 N44°18.19' W96°48.91' at fld. 1641/6E. AWOS-3.

VOR portion unusable:

116°-129° byd 10 NM blo 6,000'

270°-029° byd 10 NM blo 6,000'

130°-180° blo 6,000'

ILS 110.9 I-BKK Rwy 30. Class IE. Unmonitored.

